



Road Safety

Information: 1-800-333-0371

2010-C01 E

Sept 13, 2010

Baby Trend Infant Car Seats

Manufacturer:	Baby Trend 1607 South Campus Ave. Ontario CA 91761 U.S.A. Tel.: 1-800-328-7363 Website: www.babytrend.com
Importer and Distributor:	Baby Trend 1607 South Campus Ave. Ontario CA 91761 U.S.A.
Consumer Contact:	Tel.: 1-800-328-7363
Model and Model Numbers Affected:	EZ-Flex Infant Car Seat-Limestone – CC13797 Flex-Loc Infant Car Seat-Mojito – CC21428 Expedition Travel System-Ion – TJ94073 Sit-N-Stand Deluxe Travel System-Vanguard – TN74740
Dates of Manufacture:	2009/11/28 – 2010/03/10
Number of Units	10,276
Geographic Distribution:	Across Canada

Issue:

Baby Trend and Transport Canada wish to inform the public that the above models of infant restraint systems are non-compliant with sub-section 7 (f)(i) (currently subsection 316(1)(e)(i)) of the *Motor Vehicle Restraint Systems and Booster Seats Safety Regulations*. The regulations specify that each infant restraint system must be affixed with a specific warning that the infant restraint is for use only in a **forward-facing vehicle seat** equipped with a lower universal anchorage system or with a vehicle safety belt. The subject models do not contain the requisite warning.

The Owner's manual included with the infant car seats correctly states all warnings and clearly defines and illustrates both proper and improper vehicle seating positions for installation and use of the infant car seat. The manual also states for the consumer to contact the vehicle manufacturer if they have any questions regarding installation in their particular situation.

The labels have been revised and the problem corrected. In addition, Baby Trend has advised that it is not aware of any incidents related to this issue in Canada or the United States.

Baby Trend and Transport Canada wish to inform all parents and caregivers of the omission so as to eliminate any possibility of installing the infant restraint in either a side or rear-facing seat.

Background and Company Action:

The non-compliance was noted during the annual testing and audit inspection program conducted as part of Transport Canada's safety compliance assessment program. The company was notified of the technical non-compliance and Baby Trend will provide a free label replacement kit and detailed instructions to all registered owners.

Consumer Action and Recourse:

Consumers that have not registered their restraint system are advised to contact Baby Trend at **1-800-328-7363** so that the company can also send them a free label replacement kit and detailed instructions. Owners that are uncertain about whether or not they have registered their unit should contact Baby Trend at the above number.

Until the non-compliant label is replaced, the restraint system can continue to be used in accordance with the instructions found in the manual. The affected restraint systems should not be returned to the Baby Trend retailer.

Transport Canada: 1-800-333-0371

Release Date: September 13, 2010

Sièges pour bébé Baby Trend

Fabricant	Baby Trend 1607 South Campus Ave. Ontario CA 91761 U.S.A. Tél. : 1-800-328-7363 Site Web : www.babytrend.com
Importateur et distributeur :	Baby Trend 1607 South Campus Ave. Ontario CA 91761 U.S.A.
Service à la clientèle	Tél. : 1-800-328-7363
Modèle et numéros de modèles visés	EZ-Flex Infant Car Seat-Limestone – CC13797 Flex-Loc Infant Car Seat-Mojito – CC21428 Expedition Travel System-Ion – TJ94073 Sit-N-Stand Deluxe Travel System-Vanguard – TN74740
Dates de fabrication	2009/11/28 – 2010/03/10
Nombre d'unités	10 276
Distribution géographique	Partout au Canada

Problème :

Baby Trend et Transport Canada souhaitent informer le public que les modèles ci-dessus d'ensembles de retenue pour enfants ne sont pas conformes au sous-alinéa 7(f)(i) (actuellement sous-alinéa 316 (1) (e)(i)) du *Règlement sur la sécurité des ensembles de retenue et des sièges d'appoint (véhicules automobiles)*. Le règlement stipule que chaque ensemble de retenue pour bébé doit porter une étiquette avertissant le public que l'ensemble ne doit être utilisé que sur un siège **orienté vers l'avant du véhicule** et équipé d'un dispositif universel d'ancrages d'attaches inférieurs ou d'une ceinture de sécurité. Cet avertissement n'est pas affiché sur ces modèles.

Le manuel du propriétaire inclus avec l'ensemble de retenue pour bébés indique justement tous les avertissements et illustre les places assises du véhicule appropriées et inappropriées pour l'installation et l'usage de l'ensemble de retenue pour bébés. Le manuel informe aussi aux consommateurs de contacter le fabricant de véhicule lors de questions concernant l'installation dans leur cas particulier.

L'étiquette a été révisée et le problème est corrigé. En plus, Baby Trend nous a averti qu'il n'est pas conscient d'aucun incident relié à cette question au Canada ou aux États-Unis.

Baby Trend et Transport Canada souhaitent informer les parents et responsables de l'omission pour éliminer la possibilité d'installer l'ensemble de retenue pour bébé sur un siège orienté vers le côté ou l'arrière du véhicule.

Contexte et mesure prise par l'entreprise :

La non-conformité a été décelée lors du programme d'inspection et de vérification annuel mené dans le cadre du programme d'évaluation de la conformité en matière de sécurité de Transports Canada. La compagnie a été avisée de la non-conformité technique et elle fournira gratuitement une trousse de remplacement des étiquettes, ainsi que des instructions détaillées à tous les propriétaires inscrits.

Recours des consommateurs :

Les consommateurs qui n'ont pas inscrit leur ensemble de retenue doivent contacter Baby Trend au **1-800-328-7363** afin que la compagnie puisse leur envoyer gratuitement une trousse de remplacement des étiquettes et des instructions détaillées. Les propriétaires qui ne savent pas s'ils ont inscrit leur unité devraient contacter Baby Trend au numéro susmentionné.

Jusqu'au remplacement de l'étiquette non-conforme, l'ensemble de retenue peut continuer à être utilisé en suivant les instructions figurant dans le manuel. Les ensembles de retenus concernés ne devraient pas être retournés au détaillant de Baby Trend.

Transports Canada : 1-800-333-0371

Date de l'avis : Le 13 septembre 2010